

DAILY SERVICE DELIVERY OVERVIEW

SATURDAY, October 02, 2010

1. RUNS PULLED OUT- IN SERVICE:

	SCHEDULED	PULLED OUT IN SERVICE %	RUNS NON OUT	RUNS WORKED AT OVER TIME
SYSTEM WIDE	798	97.9	17	43

2. VEHICLES AVAILABILITY

	SCHEDULED	AVAILABLE	SPARE RATIO
LRV	57	98	72%
F LINE	19	21	11%
CABLE CAR	25	29	16%
WOODS	64	110	72%
KIRKLAND	63	107	70%
FLYNN	78	105	35%
POTRERO 40'	34	45	32%
POTRERO 60'	39	40	3%
PRESIDIO	66	122	85%
TOTAL	445	677	52%

3. OPERATORS' ABSENTEEISM:

	Scheduled WF	Total Unavailable	Sick	Vacation	Unplanned Leave	Other Reasons
Green	156	33	4	4	15	10
Cable Car	105	26	6	6	9	5
Potrero	168	45	7	5	22	11
Presidio	138	22	6	4	6	6
Kirkland	139	30	2	6	12	10
Woods	236	38	9	2	19	8
Flynn	166	42	4	10	20	8
TOTAL	1,108	236	38	37	103	58

4. ACCIDENTS & DELAYS > 20 MINUTES:

ACCIDENTS:

TIME DATE	CALL FROM DIVISION	TO CC	OP#	RUN	LINE	VEH	LOCATION	NATURE OF OCCURRENCE ACTION TAKEN	DELAY			
									DI	START	END	CC
11:55 10/02/10	R OPERATOR KI	17	3655	565	5	8327	FULTON & 8TH AVE. (OB)	ACCIDENT COACH AND AUTO	OB	11:55	12:45	11
							1129786	INSP.VICKERS,E.CLAIMS *,SYSTEM SAFETY * NO 799 MINOR DAMAGE AUTO VEH DELAY: 00:50				
15:44 10/02/10	R OPERATOR PO	18	3509	430	22	5451	FILLMORE & SUTTER (OB)	NON INJURY ACCIDENT, COACH / AUTO.	OB	15:44	16:50	24
							1129857	INSP WONG S, 1L2*, VIDEO*, CLAIMS #6A01*, S/S*, NO 799 VEH DELAY: 01:06				
19:30 10/02/10	R OPERATOR FL	15	2167	529	71	6254	HAIGHT & DIVISARDERO (OB)	ACCIDENT (COACH / AUTO) NO INJURIES	OB	19:30	20:42	16
							1129884	INSP A. GEETER RESPONDED, REPORT OF AUTO MADE CONTACT WITH LEFT FRONT SIDE OF COACH, VIDEO*, NO 799 SI FLYNN EOR @00:00N/R [EOR 20:41] VEH DELAY: 01:11				

LINE DELAY > 20 MINUTES:

TIME DATE	CALL FROM DIVISION	To CC	OP#	RUN	LINE	VEH	LOCATION	NATURE OF OCCURRENCE ACTION TAKEN	DELAY			
									DI	START	END	CC
14:57 10/02/10	R OPERATOR CA	26	1803	16	54	20	POWELL STREET & MARKET STREET (IB)	CAR STUCK ON THE TABLE (BROKEN WOOD)	IB LD	14:57 14:57	15:25 15:25	27
				1129803			INSP. KWONG (8T54), INSP. BARTH 8T43*, DISPATCHER*, SHOP TRUCK 665, CABLE MACHINERY, D. BANBURY*, CAR WAS TOWED IN BY SHOP TRUCK #665, PAGED @1530 AND FINAL @1543 SI CABLE CAR N/R VEH DELAY: 00:28 LINE DELAY: 00:28					